

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Ops & Trng

Trng Rngs & Areas

Live Fire Ranges

Mout Assault Cs

Live Fire Shoot

F2/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	218	W1H1AA-04

F3/Q1

Broken window due to CAT 5 Hurricane Maria on September 2017.

4988	219	W1H1AA-04
------	-----	-----------

F2/Q1

4988	220	W1H1AA-04
------	-----	-----------

F2/Q1

Trng / Instr Fac

Gen Instr Facilities

Gen Inst Bldgs

Gen Inst Bldg

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	1309	W1H1AA-00

F4/Q4

Trng / Trng Sup Facilities

Tasc

Tng Aids Ctr

F2/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	511	W1H1AA-10

F2/Q1

Damage caused by CAT 5 hurricane Maria, September 2017, includes - Roof New fascia and AC unit mini-split.

Org Classroom

Org Classroom

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
----------------	--------------	------------

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	511	W1H1AA-PL	F1/Q1	Damage caused by CAT 5 hurricane Maria, September 2017, includes - Roof New fascia and AC unit mini-split.
4988	546	WTJ2AA-00	F1/Q1	Damage caused by CAT 5 hurricane Maria, September 2017, includes - Acoustical ceiling 2' x 4' - 21 each needs replacement. Filtration from ceiling affecting beam. Beam has started to corrode. Office C-110 Wall corner presence of mold. Male and female bathrooms has mold growing in gypsum board ceiling."

Simulator Facs

Sim Center

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>		
4988	548	WTJ2AA-00	F1/Q1	Damage caused by CAT 5 hurricane Maria, September 2017, includes - Roof flashing removed (20 ft) south side. Acoustical ceiling 2' x 4' at aisle - 6 need replacement. Old GYM - corrosion in metal ceiling and metal door seals and bottoms - weather stripping need replacement. Approximately 10 lf of siding and gutter need replacement.

Trng Cntrs - Arng / Usar

Tng Cntrs-Reserv

Usar Center

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>		
4988	1029	W76CAA-	F4/Q3	
4988	1030	W8CEAA-	F4/Q3	
4988	1031	WRQLAA-27	F4/Q3	
4988	1032	WRQLAA-27	F4/Q3	
4988	1033	W1H1AA--S	F4/Q3	

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Doors need replacement, drainage needs to be corrected. Exterior damage caused by CAT 5 hurricane Maria, September 2017 includes roof damage, interior hung ceiling damage, water filtrations and exterior door damage.

4988	1034	UNASGD	F4/Q3	Storage facility abandoned in place
4988	1035	W1H1AA--S	F4/Q3	
4988	1036	W8CEAA-	F4/Q3	
4988	1037	WRYAAA-	F4/Q3	
4988	1038	WRYAAA-	F4/Q3	
4988	1039	WSZ2AA-	F4/Q3	
4988	1041	W8CEAA-	F4/Q3	Old Elementary School restrooms
4988	1042	W8CEAA-	F4/Q3	
4988	1043	UNASGD	F4/Q4	Old Elementary school GYM partially destroyed by hurricane Maria.
4988	1044	UNASGD	F4/Q3	Small storage shed.
4988	1054	W8CEAA-	F4/Q4	Restrooms abandoned in place.
4988	1055	UNASGD	F4/Q3	Small isolated electrical room, no locking door, poor conditions, old equipment abandoned in place.
4988	1056	W8CEAA-1S	F4/Q3	
4988	1061	W1H1AA-	F4/Q3	Small electrical closet.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	1302	W1H1AA-00	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1304	UNASGD-	F4/Q4	Facility is set for demolition as part of the FRP FY16. Abatement has been completed as of November 2017. Demolition pending NTP.
4988	1306	UNASGD-	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1308	WRQLAA-00	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1309	W8CEAA-00	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1310	UNASGD-	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1311	WSKVAA-00	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1312	UNASGD-	F4/Q4	Facility is set for demolition as part of the FRP FY16. Abatement has been completed as of November 2017. Demolition pending NTP.
4988	1313	UNASGD-	F4/Q4	Facility is set for demolition as part of the FRP FY16. Abatement has been completed as of November 2017. Demolition pending NTP.
4988	1314	UNASGD-	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	1317	W72502-00	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>	<u>Msn-Func/Quality Rating</u>	<u>Asset Use Comments</u>
4988 1318 WSZ2AA-00	F4/Q4		Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988 223 W87LAA-00	F4/Q4		Damages caused by CAT 5 hurricane Maria, September 2017, include Roof Damages.
4988 224 W87LAA-00	F4/Q4		Damages caused by CAT 5 hurricane Maria, September 017, include roof damages.
4988 231 W87LAA-00	F4/Q4		Roof flashing removed by CAT 5 hurricane Maria, September 2017.
4988 233 W87LAA-00	F4/Q4		Roof gutters removed on north east side. Damage caused by CAT 5 hurricane Maria, September 2017.
4988 353 W8CEAA-00	F1/Q2		Damage caused by CAT 5 hurricane Maria, September 2017, includes - Flashing missing approximately 35 Linear feet of 12 inch plates on west face of building. Building cladding blown away (cosmetic damage). All downspouts missing on North and East faces of building (7 total). Carpet Cleaning.
4988 354 W8CEAA-00	F1/Q2		Damage caused by CAT 5 hurricane Maria, September 2017, includes - Main doors need repairs. Wind damage has lead to have bith 1st and 2nd floor main doors unusable as they are unhinged and likely to fall. One downspout on west side missing. East side missing the flashing (approximately 40 linear feet of 12 inche plates. 60 linear feet of gutter missing.
4988 355 W8CEAA-00	F2/Q2		Damages caused by CAT 5 hurricane Maria, September 2017 include - Water leaks from roof, floor plate missing on exterior door to gym. Rainwater gets into the building. Gutter damaged. Carpet damaged.
4988 356 W8CEAA-00	F1/Q2		
4988 357 W8CEAA-00	F2/Q2		

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	507	WSS3AA-00	F2/Q4	Gutters and downspouts damaged by CAT 5 hurricane Maria, September 2017.
4988	512	WR0ZAA-00	F4/Q1	
4988	514	WR0ZAA-00	F3/Q3	
4988	523	W8CEAA-00	F1/Q4	Roof damaged by CAT 5 hurricane Maria, September 2017.
4988	525	W8CEAA-00	F1/Q4	Facility gutters damaged by CAT 5 hurricane Maria, September 2017.

Arm Force Ctr

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	315	WQ2QAA-00	F1/Q1

Tng Ctrs-Ng/Ar

Arng/Usar Ctr

F2/Q2/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	73	N68702-00	F2/Q2
4988	74	N68702-00	F2/Q2
			Water inside Command SVC Office and downspouts blown out. Damage caused by CAT 5 hurricane Maria, September 2017.
4988	75	N68702-00	F2/Q2
			Water inside Class room voluntary training unit and classroom #5. Damage caused by CAT 5 hurricane Maria, September 2017.
4988	77	N68702-00	F2/Q2
			Roof facia, gutters, downspout, front canopy damage. Hallway electrical conduit damage. Mildew issues. Damage caused by CAT 5 hurricane Maria, September 2017.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	78	N68702-00	F1/Q2	Roof fascia damages caused by CAT 5 hurricane Maria, September 2017.
------	----	-----------	-------	--

Tng Ctrs - Ng

Arng Armory

F2/Q2/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>		
4988	1309	W7PAAA-00	F4/Q4	Facility is currently vacant and awaiting demolition as part of the FRP for FY17.
4988	540	UNASGD-	F3/Q3	Roof damaged due to CAT 5 Hurricane Maria.
4988	541	UNASGD-	F3/Q2	
4988	545	WTJ2AA-00	F1/Q1	Damage caused by CAT 5 hurricane Maria, September 2017, includes - Acoustical Ceiling 2' x 2' - 45 each need replacement. Metal door - glass opening broken (6" x 1'-6"). Female bathroom shower area - filtration from the second floor. Windows - seepage from exterior - needs to be sealed (13 windows). Windows - broken glass - needs to be replaced (1 each).
4988	552	W8BC!A-	F1/Q2	Damages caused by CAT 5 hurricane Maria, September 2017, include - HVAC issues on JOC room and Roof damages.
4988	563	UNASGD-	F3/Q3	Facility has roof and interior damage caused by CAT 5 hurricane Maria, September 2017.
4988	607	UNASGD-	F4/Q4	

Admin Fac (Ops & Trng)

Unit Ops Bldgs (Ops & Trng)

Ops Spt Bldgs

Access Cnt Fac

F4/Q1/NA

SITEUID FACNO UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	25	W1H1AA-04	F4/Q1	Roof, gutters and downspouts and facia. Exterior tiles damaged. Traffic arms affected. CAT 5 Hurricane Maria September 2017.
4988	28	W1H1AA-04	F4/Q1	Roof, gutters and downspouts and fascia damage due to CAT 5 Hurricane Maria, September 2017.
4988	665	W1H1AA-04	F4/Q1	Damage caused by CAT 5 hurricane Maria, September 2017, includes entire canopy destruction.
4988	670	W1H1AA-04	F4/Q1	

Animal Shelter

Wk Animal Bldg

F4/Q4/NA

SITEUID

FACNO

UIC

4988

291

W1H1AA-04

F4/Q4

Facility was demolished

Info Mangmnt

Information Management

Info Sys Facs

Info Sys Fac

F1/Q3/NA

SITEUID

FACNO

UIC

4988

514

W1H1AA-10

F4/Q3

Damage caused by CAT 5 hurricane Maria, September 2017, includes mini-split AC and duct work.

4988

527

W6SAAA-NE

F1/Q3

Emergency power required but not available including uninterrupted power supply. Damage caused by CAT 5 hurricane Maria, September 2017 includes - Roof and duct work. Mildew Cleaning. AC duct damaged. Ceiling tile frame and replace ceiling tile. Roof leak male bathroom.

Commo Ctr

F3/Q4/NA

SITEUID

FACNO

UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988 376 W6SAAA-NE

F3/Q4

Damage caused by CAT 5 hurricane Maria, September 2017 includes - missing one downspout, Roof flashing blown on northeast corner (approximately 20 linear feet) Damaged canopy. AC and cameras were affected. Domestic electrical pole needs to be repaired, missing gutter. Door magnets at main entrance are damaged

Info Sys Proc

F1/Q1/NA

SITEUID FACNO UIC
4988 611 W1H1AA-41

F1/Q1

Print Plant

Print Plant

NA/NA/NA

SITEUID FACNO UIC
4988 514 ISYS23-DL

NA/Q3

Rated by Business Rule

Maint & Prod

Maint Fac

Maint Facilities

Veh Maint Trans

Veh Maint Tt

F1/Q1/NA

SITEUID FACNO UIC
4988 550 WTJ2AA-00

F1/Q1

Damage caused by CAT 5 hurricane Maria, September 2017, includes - garage roll up door wall insulation needs replacement. Ridgepole - visible filtration from ceiling. Roof over metal column 0 visible filtration from ceiling. Roof siding, gutter and metal roof need replacement. Exterior luminaries need replacement.

Ar Maint Facs

Usar Veh Maint

F1/Q1/NA

SITEUID FACNO UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	528	W8CEAA-00	NA/NA	Damage caused by CAT 5 hurricane Maria, September 2017, includes exterior lighting and gutters.
4988	615	WQ2QAA-00	NA/NA	
4988	616	WQ2QAA-00	NA/NA	

Veh Maint Shops

Veh Maint Shop

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	609	UNASGD-

F1/Q1

Veh Mnt Dol/Deh

Mnt Gen Purpose

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	607	UNASGD-

F4/Q4

Inst Mnt/Rep

Eng/Housing Mnt

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	37	W1H1AA-12

F1/Q1

Repair double metal door and cyclone fence, damage caused by CAT 5 hurricane Maria, September 2017.

Entomology Fac

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	38	W1H1AA-12

F1/Q1

Acoustice ceiling tiles and replace lamps. Damage caused by CAT 5 Hurricane Maria, September 2017.

Supply

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Supply & Storage Fac

Operational Fuel Fac

Veh Fuel Facs

Veh Fuel Mogas

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	613FM	W1H1AA-DP

F1/Q1

Veh Fuel Diesel

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	613FD	W1H1AA-DP

F1/Q1

Veh Fuel Stor

Mogas Str Ungd

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	VF677	IAAFES-00

F1/Q1

Mogas Str Abv

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	613TM	W1H1AA-DP

F1/Q1

Diesel Str Abv

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	613TA	W1H1AA-DP

F1/Q1

4988	613TB	W1H1AA-DP
------	-------	-----------

F1/Q1

4988	613TC	W1H1AA-DP
------	-------	-----------

F1/Q1

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	HF550	W!RQZP-	F1/Q1
------	-------	---------	-------

Ammo Storage Fac

Inst Ammo Stor

Fuse/Det Mag In

F4/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	297	W1H1AA-04	F4/Q3

Gen Supply & Stor Fac

Haz Stor Depot

Haz Mat Str Dep

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	HM037	W1H1AA-12	F1/Q1

Encl Stor Inst

Storage Gp Inst

F2/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	504	W1H1AA-09	F4/Q4
4988	509	W1H1AA-09	F2/Q2
4988	512	UNASGD	F3/Q3
4988	521	W1H1AA-09	F4/Q3
4988	547	WTJ2AA-00	F1/Q1

Damage caused by CAT 5 hurricane Maria, September 2017, includes roof fascia, and transformer damage.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Damage caused by CAT 5 hurricane Maria, September 2017, includes - Damage roof flashing (70 ft) east side. Bended roof flashing (20 ft) south side. Supply B-180 room has water seepage from ceiling. Male bathrooms has mold on gypsum board ceiling."

4988 608 W1H1AA-DF

F3/Q4

4988 613 UNASGD-

F3/Q4

Exterior are in poor condition (mold, paint, water leaks). Building walls need patching and painting. Loading dock does not have any railing to prevent forklift from falling off the dock. Fire Protection components not tested. No paved sidewalks. Additional roof damaged caused by CAT 5 hurricane Maria, September 2017.

Arms Storage-Bn

Arms Storage-Bn

F4/Q4/NA

SITEUID FACNO UIC
4988 539 W1H1AA-01

F4/Q4

There are no parking areas. The loading area is no adequate. There are no bathroom facilities. Facility suffered roof damage caused by CAT 5 hurricane Maria, September 2017.

Unit Stor Bldgs

Org Str Bldg

F1/Q1/NA

SITEUID FACNO UIC
4988 553 W1H1AA-DP

F1/Q1

4988 564 W1H1AA-37

F3/Q2

4988 565 W1H1AA-37

F3/Q2

4988 619 UNASGD-

F1/Q1

Haz Stor Inst

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Haz Mat Str Ins

F3/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	267	W1H1AA-04

F4/Q4

Metal roof was completely damaged by CAT 5 hurricane Maria, September 2017.

4988	558	W1H1AA-12
------	-----	-----------

F3/Q3

Flam Mat Str In

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	549	WTJ2AA-00

F1/Q1

Vehicle Storage

Veh Str Shed In

F1/Q2/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	237	W1H1AA-04

F2/Q3

Facility do not provide adequate storage.

4988	389	W1H1AA-00
------	-----	-----------

F1/Q1

Medical

Hospital & Medical Fac

Veterinary Fac

Veterinary Facs

Vet Facility

NA/NA/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	676	UNASGD-

NA/Q1

Rating restored from FY17 Q4

Dispensaries And Clinics

Clinics

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Health Clinic

NA/NA/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	21	W3QM03-00

NA/Q1

Facility suffered major roof and interior damage due to CAT 5 Hurricane Maria in September 2017.

4988	228	W3QM03-00
------	-----	-----------

NA/Q1

Administrative

Admin Fac (Admin)

Gp Admin Facilities

Eoc/Scif Facs

Emerg Opns Cntr

F2/Q2/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	390	W1H1AA-DP

F2/Q2

Damages caused by CAT 5 hurricane Maria, September 2017, include - Roof repairs need to be done. Ceiling tile replacemnet at 3rd floor PAIO and 2nd floor IOC. Glass doors are not operational and can not get secured.

Admin Facs

Admin Gen Purp

F3/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	1057	UNASGD

F4/Q3

4988	1300	W1H1AA-
------	------	---------

F4/Q4

Facility is currently vacant and awaiting demolition as part of the FRP for FY17.

4988	1301	W1H1AA-30
------	------	-----------

F4/Q3

Facility is currently vacant and awaiting demolition as part of the FRP for FY17.

4988	136	W1H1AA-DF
------	-----	-----------

F3/Q3

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>			<u>Msn-Func/Quality/Quantity Rating</u>
			<u>Msn-Func/Quality Rating</u>
			<u>Asset Use Comments</u>
4988	152	W1H1AA-41	F3/Q3
4988	192	W1H1AA-07	F3/Q2 Roof damage caused by CAT 5 hurricane Maria, September 2017.
4988	193	W1H1AA-36	F1/Q2
4988	204	W1H1AA-13	F4/Q3 Roof flashing loose, mold in several locations and acoustic ceiling had water in several places due to CAT 5 Hurricane Maria on September 2017.
4988	214	W1H1AA-31	F3/Q3 Damages caused by CAT 5 hurricane Maria, September 2017 include - Roof metal sheets removed (north side). Palm tree down on north side.
4988	227	UNASGD	F3/Q1
4988	34	W1H1AA-12	F1/Q1 Storm shutter needs repair or replacement on main door of south side of the building. Wet Carpet at Building Entrance. Damage caused by CAT 5 hurricane Maria, September 2017.
4988	390	W1H1AA-00	F1/Q3 Damages caused by CAT 5 hurricane Maria, September 2017, include - Roof damage/leaks. Ceiling tile replacement at 3rd floor PAIO and 2nd floor IOC. Glass doors are not operational and can not get secured.
4988	504	W1H1AA-09	F1/Q3
4988	509	W1H1AA-09	F3/Q2
4988	512	W4ZG01-00	F3/Q3 Damage caused by CAT 5 hurricane Maria, September 2017, includes roof fascia, and transformer damage.
4988	514	W1H1AA-01	F3/Q3

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Damage caused by CAT 5 hurricane Maria, September 2017, includes mini-split AC and duct work.

4988 519 W1H1AA-

F3/Q3

Damage caused by CAT 5 hurricane Marina, September 2017 includes - Roof, damaged ceiling tiles

4988 566 IEPRAN-01

NA/Q1

4988 607 UNASGD-

F4/Q4

4988 79 W1H1AA-01

F2/Q4

Roof fascia damage caused by CAT 5 hurricane Maria, September 2017..

4988 80 W1H1AA-01

F4/Q4

4988 81 W1H1AA-01

F4/Q2

4988 82 W1H1AA-01

F4/Q4

Hsg & Community

Family Housing

Family Housing Dwelling

Fam Hsg Dwell

Fh Col

F4/Q4/NA

SITEUID

FACNO

UIC

4988

809

W1H1AA-15

F4/Q4

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes Storage shed destroyed, solar water heater.

4988

814

W1H1AA-15

F4/Q4

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes 30FT fascia damage, storage shed destroyed, 300ft lattice destroyed, 15 ft chain link fence destroyed.

4988 816 W1H1AA-15

F4/Q4

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

4988 818 W1H1AA-15

F4/Q4

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes Roofing (60' by 10').

4988 821 W1H1AA-15

F4/Q4

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

4988 825 W1H1AA-15

F4/Q3

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

Fh Ltc/Maj

F4/Q4/NA

SITEUID FACNO UIC

4988 803 W1H1AA-15

F4/Q4

MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

4988 804 W1H1AA-15

F4/Q4

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	805	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	806	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	807	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	808	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	810	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	811	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	812	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	813	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	815	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes Fascia damage 15ft, 100ft lattice storage shed destroyed.
4988	817	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	819	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes 50ft lattice, storage shed destroyed, solar water heater.
4988	820	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	822	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	823	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	824	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	827	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAY 5 hurricane Maria, September 2017 includes 20ft fascia, storage shed, 50 ft lattice.
4988	828	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	829	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes Storage shed, kitchen entrance canopy.
4988	830	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017, includes Storage shed, 10ft fascia.
4988	831	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

Fh Co/WO

F4/Q4/NA

SITEUID

FACNO

UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	1127	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1129	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1132	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017, includes patio shed and electrical conduit damage.
4988	1134	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes Patio shed destroyed + damage to HVAC unit.
4988	1135	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1137	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1138	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	1139	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1149	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1152	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1154	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1155	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1158	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1161	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1162	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	1163	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>
4988	1166	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>
4988	1167	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>
4988	1168	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>
4988	1170	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>
4988	1173	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>
4988	1229	W1H1AA-15	<p>F4/Q4</p> <p>MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.</p>

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	1231	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1234	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1235	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1237	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.
4988	1239	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Coconut Grove (Built in 1955) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience.

Family Housing, Senior No

F4/Q4/NA

SITEUID

FACNO

UIC

4988	826	W1H1AA-15	F4/Q4	MCA 78348 Family Housing Replacement Construction, in the FY17 Program, will replace this Family Housing unit at Las Colinas (Built in 1948) to conform with Army Standards for health, welfare, energy conservation, maintainability, comfort and convenience. Damage caused by CAT 5 hurricane Maria, September 2017 includes Solar water heater damage 50ft lattice, storage shed.
------	-----	-----------	-------	---

Post Exchange

Post Exchange

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Mil Cloth Sale

Mil Cloth Sale

F3/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	611	103282-00

F3/Q4

Exterior damage caused by CAT 5 hurricane Maria, September 2017.

Exch Eating Fac

Fst Fd/Snk Bar

F2/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	151	UNASGD

F1/Q3

Roof and canopy. Water inside the building. Freezer got damaged. Damages caused by CAT 5 hurricane Maria, September 2017.

4988	689	103285-00
------	-----	-----------

F2/Q3

Exch Retail Fac

Exchange Branch

F1/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	677	UNASGD-

F1/Q3

Damage caused by CAT 5 hurricane Maria, September 2017 includes - Damaged Acoustic Ceiling Tiles, North fa%E7ade canopy and West fa%E7ade canopy damage, North wall canopy anchors destroyed (Wall finish damaged), West wall canopy anchors destroyed (Wall finish damaged). (5) Exterior lighting fixtures destroyed. 12%u2019 x 12%u2019 Gazebo destroyed. 15 LF Approx. decorative roof flashing damaged. Gas dispenser (1/3 & 7/5) damaged. Were pushed to the floor because of the hurricane winds. Dispenser & column signs damaged or non-existing.

Exch Main Store

F2/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	689	103280-00

F2/Q4

Exch Ser Outlet

F3/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
----------------	--------------	------------

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988 606 103281-00

F3/Q3

CAT 5 Hurricane Maria on September 2017:
 "2022 (400 units approx.) 2019 x 4019 Damaged & destroyed Acoustic Panels
 2022 (2) 2019 x 4019 lighting fixtures damaged.
 2022 (1) 1019 x 4019 interior lighting fixture damaged.
 2022 (30) Translucent cover for 2019 x 4019 lighting fixtures damaged.
 2022 (3 visible perforations) Garden Area roof damaged. Has leak stains at the bottom.
 2022 Garden area roll-up doors pulled off the wall.
 2022 (7) 2019 x 10019 outdoor sun shade net destroyed.
 2022 (1) 54019 x 10019 & (1) 13019 x 10019 North fade canopies destroyed.
 2022 Interior walls with leak water marks.
 2022 Main store, Beer storage area & Garden area has major water leaks.
 2022 North fade security camera damaged.
 2022 ICA office 2013 (2) Damaged computers.
 2022 Food coolers damaged.
 2022 (1) Broken fixed glass at storefront. At the exit doors.
 2022 (1) Women's bathroom lighting fixture damaged.
 2022 12019 x 12019 Gazebo destroyed.
 2022 12019 Hex gazebo with roof damage."

Exch Concession

F3/Q3/NA

SITEUID FACNO UIC
 4988 689 103280-00

F3/Q3

Exch Warehouse

Exch Warehouse

F3/Q3/NA

SITEUID FACNO UIC
 4988 611 103284-00
 4988 612 103284-00

F4/Q4

Exterior damage caused by CAT 5 hurricane Maria, September 2017.

F4/Q3

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

security system non-operational. Damage caused by CAT 5 hurricane Maria, September 2017 includes - South facade canopies damaged (bended structure) 13' x 22'. (2) Damaged downspouts & gutters at south facade. (4) Damaged downspouts & gutters at north facade.

4988 614 103284-00

F3/Q3

CAT 5 Hurricane Maria:
 "2022 Canopies destroyed: #1 - 20' x 10', #2 30' x 10', #3 30' x 10' & #4 46' x 10'.
 2022 Roll-up doors were pushed to the interior of the building. Employees did a temporary fix to operate them.
 2022 (#3, #4 & #5) Roll-up door exterior lighting damaged.
 2022 #1 North facade canopy destroyed.
 2022 Building powered by generator."

4988 689 103284-00

F1/Q3

Commissary

Commissary

Commissaries

Commissary

F3/Q3/NA

SITEUID FACNO UIC
 4988 689 DCE40W-CO

F3/Q3

Child Dev Ctrs

Child Develop Ctrs

Child Dev Ctrs

Cdc Under 6 Yrs

F4/Q4/NA

SITEUID FACNO UIC
 4988 1000 W1H1AA-20

F4/Q4

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

The Child Development Center (CDC), Building 1000, Fort Buchanan, Puerto Rico has experienced significant ongoing mold growth and moisture problems. In order to determine the cause, extent and possible corrective actions to address these problems, the Department of the Army NAF Contracting Office conducted, on 17 December 2013, a comprehensive forensic analysis of the CDC facility at Fort Buchanan. IMCOM G-9 proposed to build a new consolidated Child Development Center (8,423 SF) and a Middle School and Teen (MST) Center (21,206 SF) for a new requirement of 29,629 SF. The new Site at Coconut Grove Housing Area can accommodate this facility. Bldg. 1000 will be demolished upon completion of the consolidated Child Development Center and Middle School and Teen (MST) Center.

Damage caused by CAT 5 hurricane Maria, September 2017 includes - Gutter tension hangers are lose , need to be looked at 100 SF of roof underhang (soffit) went missing along the east a wall of the gym. 75 LF of roof flashing need to be replaced along the east a wall of the gym. 375 SF of roof underhang (soffit) need to be installed above the main entrance. The kitchen hood vent needs to be put back in place, as rain water enters the kitchen through the displaced hood. Still has issues with the hood."

Dep School Fac

Dep School Fac

Dependent Schl

Dependent Sch

F1/Q2/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	1060	IEPRAN-01	NA/Q2
4988	1062	IEPRAN-01	F1/Q2
4988	1064	IEPRAN-01	NA/Q2
4988	1066	IEPRAN-01	NA/Q4
4988	1068	IEPRAN-01	NA/Q2

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>			<u>Msn-Func/Quality/Quantity Rating</u>
			<u>Msn-Func/Quality Rating</u>
			<u>Asset Use Comments</u>
4988	1070	IEPRAN-01	NA/Q2
4988	1071	IEPRAN-01	NA/Q2
4988	1073	IEPRAN-01	NA/Q2
4988	1075	IEPRAN-01	NA/Q2
4988	1077	IEPRAN-01	NA/Q2
4988	1079	IEPRAN-01	NA/Q1
4988	1081	IEPRAN-01	NA/Q2
4988	1083	IEPRAN-01	NA/Q2
4988	1085	IEPRAN-01	NA/Q1
4988	1087	IEPRAN-01	NA/Q2
4988	1094	IEPRAN-01	NA/Q3
4988	1095	IEPRAN-01	NA/Q4
4988	610	IEPRAN-	NA/Q2
			Rated by Business Rule
4988	700	IEPRAN--0	NA/Q1

Sep Toilet/Shower Fac

Sep Toilet/Shower Fac

Sep Toil/Shower

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Sep Toilet/Shower

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	166	W1H1AA-24

F4/Q4

No toilets/showers, no windows ceiling damaged, no showers, no lighting, no outlets, no showers, no hot water. Damage caused by hurricane Maria, September 2017 includes extensive roof damage.

4988	181	W1H1AA-25
------	-----	-----------

F4/Q4

4988	395	W1H1AA-18
------	-----	-----------

F4/Q4

No hc access, no hot water, poor ventilation, no fire protection system, no sidewalks, roof is older than 5 years.

4988	69	W1H1AA-18
------	----	-----------

F4/Q4

Area lacks parking, exterior lighting, sidewalks, and has drainage problems. No HC access. No gutters, roof over 5 years old, mold cracks, sun damage.

Cmty Spt

Physical Fitness Ctrs

Fitness Facs

Phys Fit Ctr

F3/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	148	W1H1AA-36

F2/Q3

80 acoustic ceiling tiles need to be replaced. 16 LF of fence section that needs to be repaired. Exterior glass door. Damages caused by CAT 5 hurricane Maria, September 2017.

4988	167	W1H1AA-25
------	-----	-----------

F3/Q3

No exercise module, no fitness module. Additional damages caused by CAT 5 hurricane Maria, September 2017 include damage to water heater and roof.

Outdoor Sprts & Rec Fac

Court Areas

Court Area

F2/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
----------------	--------------	------------

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	1099	W1H1AA-15	F4/Q4	Basketball court is abandoned, backboards are rotten, hoops are rusted and broken, court surface is badly damaged.
4988	173	UNASGD-	F4/Q4	Court surface is badly cracked, no fencing, court is currently closed.
4988	174	UNASGD-	F1/Q1	
4988	175	UNASGD-	F2/Q4	Area has no fence, bathrooms and surface shows some cracks.
4988	369	W1H1AA-25	F1/Q1	
4988	374	W1H1AA-36	F4/Q4	
4988	520	W1H1AA-20	F4/Q4	
4988	567	IEPRAN-01	F1/Q1	

Playground Gp

Playground Gp

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>		
4988	1002	W1H1AA-20	F1/Q1	
4988	1100	W1H1AA-15	F4/Q4	
4988	PLY06	W1H1AA-37	F4/Q4	Facility does not exist.
4988	PLY08	W1H1AA-DP	F4/NA	Playground does not exist.
4988	PLY09	W1H1AA-DP	F4/NA	Playground does not exist.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	PLY10	W1H1AA-DP	F4/NA	Playground does not exist.
------	-------	-----------	-------	----------------------------

Baseball Fields

Baseball Field **F4/Q4/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	194	W1H1AA-25	F4/Q4

Softball Fields

Softball Field **F3/Q4/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	155	W1H1AA-25	F4/Q4
4988	360	IEPRAN-01	F4/Q4
4988	375	W1H1AA-36	F1/Q4

Mp Athletic Fld

Multi Ath Field **F4/Q4/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	F1094	IEPRAN-01	F4/Q4

Stair access to field is closed with orange plastic cloth but kids ripped it and get through to the field. Drainage from the stair access is non existent and it is all over-grown, moldy and flooded, creating a pedestrian hazard.

Outdoor Pools

Od Swim Pool **F1/Q4/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	160	W1H1AA-25	F1/Q4

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Golf Courses

Golf Cse 9-Hole

F3/Q3/NA

SITEUID

FACNO

UIC

4988

7

W1H1AA-24

F3/Q3

Rec Fac

Bowling Facs

Bowling Center

F2/Q4/NA

SITEUID

FACNO

UIC

4988

168

W1H1AA-21

F2/Q4

Roof. Acoustinc ceiling missing (some places). Damage to mini-split.Exhaust fan and duct insulation. Door damaged at the mechanical room and in the side of the auto shop. Exterior painting chipped. Damages caused by CAT 5 hurricane Maria, September, 2017.

Auto Ski Ctr

Auto Skill Ctr

F1/Q3/NA

SITEUID

FACNO

UIC

4988

159

W1H1AA-25

F1/Q3

Roof and canopy damages caused by CAT 5 hurricane Maria, September 2017.

Acs Centers

Acs Ctr

F4/Q2/NA

SITEUID

FACNO

UIC

4988

225

W1H1AA-DF

F4/Q2

Roof leaks.

Library Facs

Library Main

F3/Q4/NA

SITEUID

FACNO

UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988 518 W1H1AA-25

F3/Q4

Damage caused by CAT 5 hurricane Maria, September 2017 includes
- Roof gutters and A/C damage (Main).

Open Dining

Consol Open Din

F1/Q3/NA

SITEUID FACNO UIC
4988 660 W1H1AA-22

F1/Q3

Damage caused by CAT 5 hurricane Maria, September 2017 includes
- Main Entrance wall sign destroyed. AC damaged. Broken exterior
door (Borinquen Lounge) and roof damage.

Rec Ctr/Eqp Chk

Rec Eq Checkout

F3/Q4/NA

SITEUID FACNO UIC
4988 608 W1H1AA-DF

F3/Q4

Service Fac

Fire/Rescue Fac

Fire Station

F4/Q3/NA

SITEUID FACNO UIC
4988 1321 W1H1AA-14

F4/Q3

Facility currently used as Fire Station does not meet current standards according to UFC 4-730-10. Facility is in critical condition and not suitable for Fire Station mission. It was built in 1941 as barracks and has undergone extensive patch up work. Damage caused by CAT 5 hurricane Maria, September 2017, included roof damage to vehicle storage area.

4988 399 W1H1AA-14

F4/Q3

Police/Mp Sta

Police/Mp Sta

F3/Q4/NA

SITEUID FACNO UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	202	W1H1AA-04	F3/Q4	
4988	203	W1H1AA-04	F1/Q4	Roof damaged and acoustic ceiling tiles due to CAT 5 Hurricane Maria on September 2017.
4988	206	W1H1AA-04	F3/Q4	There is no loading dock, work areas do not meet mission, emergency power and sprinklers are not available and lounge is not available. Damage caused by CAT 5 hurricane Maria, September 2017 includes - Communication antenna destroyed, palm tree fell on top of west side roof, north entrance cover removed, damaged eiling tiles and screens.
4988	212	W1H1AA-04	F1/Q4	There is no loading dock, work areas do not meet mission, emergency power and sprinklers are not available and lounge is not available. The Operation/detention areas do not meet DES standards.
4988	399	W1H1AA-04	F4/Q3	Damage caused by CAT 5 hurricane Maria, September 2017 includes, severe roof damage. 3,200 SF inside the building with severe damages (Fire Department side). Includes: all ceiling tiles damaged, gypsum board walls need selective replacement of water damage. In addition, on the Police Department side: 16 doors water damaged - need replacement. 975 SF of carpet need to be removed and replaced. 3,500 of vinyl floors might need replacement if water damage continues.

Religious Facs

Chapel

F2/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	183	W1H1AA-02

F2/Q3

No LAN connections available, Mold trough lobby and admin areas, carpet needs replacing, roof leaks near altar area, benches need replacement.

Relig Ed Facs

Relig Ed Fac

F2/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
----------------	--------------	------------

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988 292 W1H1AA-02

F2/Q3

Mold issues coming through floor tiles, no LAN or phone lines available, restroom at outside of facility.

Lndry/Drycl Fac

Laundry/Dry Cln

F3/Q3/NA

SITEUID FACNO UIC
4988 611 103280-00

F3/Q3

Exterior damage caused by CAT 5 hurricane Maria, September 2017.

Miscellaneous Support Fac (Hou

Pro Shop/Golf

Sports Pro Shop

F1/Q1/NA

SITEUID FACNO UIC
4988 171 W1H1AA-24

F1/Q1

Roof damage caused by CAT 5 hurricane Maria, September 2017.

4988 172 W1H1AA-24

F1/Q1

Golf Cse Maint

F1/Q1/NA

SITEUID FACNO UIC
4988 138 W1H1AA-24

F1/Q1

Roof gutter downspout. Damaged overhang. CAT 5 hurricane Maria, September 2017.

Rec Spt Fac

Rec Spt Fac

F1/Q4/NA

SITEUID FACNO UIC
4988 161 W1H1AA-25

F1/Q4

Roof damage, roof water channel missing. Inside corridor gypsum ceiling damaged. Bathrooms gypsum ceiling destroyed. Light fixtures fallen. Ceiling water leaks on kitchen. Damages caused by CAT 5 hurricane Maria, September 2017.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988 372 W1H1AA-36

F1/Q1

Damage caused by CAT 5 hurricane Maria includes Roof flashing blown out on north face (approximately 35 linear feet).

Util & Ground Improv

Utility Buildings

Utility Building

Pit/Util Bldgs

Pwr Pit Bldg

F2/Q4/NA

SITEUID

FACNO

UIC

4988

22

W3QM03-00

F2/Q4

Roof damaged due to CAT 5 Hurricane Maria September 2017.

Sub/Swit Sta Bd

F1/Q3/NA

SITEUID

FACNO

UIC

4988

143

W1H1AA-13

F1/Q1

4988

144

W1H1AA-13

F1/Q1

4988

379

W6SAAA-NE

F1/Q3

Damage caused by CAT 5 hurricane Maria, September 2017, includes roof missing, door and gutters damaged.

4988

TR076

N68702-00

F3/Q4

Ref/A-C Bldg

F1/Q1/NA

SITEUID

FACNO

UIC

4988

701

W1H1AA-DP

F1/Q1

Wtr Sup/Trt Bld

F3/Q4/NA

SITEUID

FACNO

UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
	<u>Msn-Func/Quality Rating</u>
	<u>Asset Use Comments</u>

4988	16	W1H1AA-PW	F4/Q4
4988	255	W1H1AA-PW	F2/Q4
4988	31	W1H1AA-13	F3/Q4
4988	371	W1H1AA-PW	F2/Q3
4988	384	UNASGD	F3/Q4
4988	702	W1H1AA-DP	F1/Q1

Water Supply Building, Nonpota **F1/Q1/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	121	W1H1AA-13	F4/Q3
4988	316	W1H1AA-13	F1/Q1

Wtr Stor Bldg **F1/Q1/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	WS551	W!RQZP-	F1/Q1

Heat / Ac

Heat / Air Cond Distrib

Chil Wtr Lines

Chil Wat Dis Sy **F1/Q1/NA**

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	35	W1H1AA-13	F1/Q1

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
	<u>Msn-Func/Quality Rating</u>
	<u>Asset Use Comments</u>

4988	CH315	W1H1AA-13	F1/Q1
------	-------	-----------	-------

4988	CH545	W1H1AA-DP	F1/Q1
------	-------	-----------	-------

Electric / Gas

Electric Source

Electrical Power Source

Elect Pwr-Photv	F1/Q1/NA
-----------------	----------

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	EP034	W1H1AA-13	F1/Q1

Standby Pwr

Standby Gen	F1/Q1/NA
-------------	----------

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	695	103280-00	F1/Q1
4988	G0034	W1H1AA-13	F1/Q1
4988	G0103	W1H1AA-13	F1/Q1
4988	G0163	W1H1AA-13	F1/Q1
4988	G0212	W1H1AA-13	F1/Q1
4988	G0399	W1H1AA-13	F3/Q2
4988	G0541	W7PAAA-00	F1/Q1
4988	G0606	103280-00	F1/Q1

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
	<u>Msn-Func/Quality Rating</u>
	<u>Asset Use Comments</u>

4988	G0673	\$1H135-00	F1/Q1
4988	G0677	103280-00	F1/Q1
4988	GO545	W!RQZP-	F1/Q1
4988	GO552	W1H1AA-DP	F1/Q1

Electric Distribution

Power Lines

Oh Elect Lines F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	DS354	W1H1AA-13	F1/Q1
4988	EL552	W1H1AA-DP	F1/Q1

Ext Lighting

Ext Lighting F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	613EL	W1H1AA-DP	F1/Q1
4988	EL353	W1H1AA-13	F1/Q1
4988	EL359	W1H1AA-13	F1/Q1

Ung Elect Lines

Ung Elect Lines F2/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	UE163	W1H1AA-13	F2/Q1

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	UE552	W1H1AA-DP	F1/Q1
------	-------	-----------	-------

Electric Substations

Substation

Substation			F1/Q1/NA
-------------------	--	--	-----------------

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	142	W1H1AA-13	F1/Q1

Transformers

Transformers			F2/Q1/NA
---------------------	--	--	-----------------

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	1001	W1H1AA-13	F1/Q1
4988	149	W1H1AA-13	F4/NA
4988	162	W1H1AA-13	F1/NA
4988	169	W1H1AA-13	F4/NA
4988	578	W1H1AA-13	F1/NA
4988	662	W1H1AA-13	F4/NA
4988	663	W1H1AA-13	F4/NA
4988	86	W1H1AA-13	F4/NA
4988	TF364	W1H1AA-13	F4/NA

Replace canopy damaged by CAT 5 hurricane Maria, September 2017.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
	<u>Msn-Func/Quality Rating</u>
	<u>Asset Use Comments</u>
4988 TR101 W1H1AA-13	F3/Q1
4988 TR102 W1H1AA-13	F4/NA
4988 TR107 W1H1AA-13	F4/NA
4988 TR108 W1H1AA-13	F1/NA
4988 TR111 W1H1AA-13	F1/NA
4988 TR112 W1H1AA-13	F4/NA
4988 TR113 W1H1AA-13	F4/NA
4988 TR115 W1H1AA-13	F1/NA
4988 TR116 W1H1AA-13	F1/NA
4988 TR117 W1H1AA-13	F1/NA
4988 TR118 W1H1AA-13	F1/NA
4988 TR119 W1H1AA-13	F1/NA
4988 TR120 W1H1AA-13	F1/NA
4988 TR123 W1H1AA-13	F4/Q1
4988 TR125 W1H1AA-13	F1/NA

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
	<u>Msn-Func/Quality Rating</u>
	<u>Asset Use Comments</u>
4988 TR127 W1H1AA-13	F1/NA
4988 TR141 W1H1AA-13	F1/NA
4988 TR143 W1H1AA-13	F4/NA
4988 TR144 W1H1AA-13	F4/NA
4988 TR145 W1H1AA-13	F1/NA
4988 TR146 W1H1AA-13	F1/NA
4988 TR147 W1H1AA-13	F1/NA
4988 TR149 W1H1AA-13	F4/NA
4988 TR150 W1H1AA-13	F4/NA
4988 TR151 W1H1AA-13	F4/NA
4988 TR152 W1H1AA-13	F4/NA
4988 TR200 W1H1AA-13	F4/NA
4988 TR201 W1H1AA-13	F4/NA
4988 TR202 W1H1AA-13	F4/NA
4988 TR203 W1H1AA-13	F4/NA

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>			<u>Msn-Func/Quality/Quantity Rating</u>
			<u>Msn-Func/Quality Rating</u>
			<u>Asset Use Comments</u>
4988	TR204	W1H1AA-13	F4/NA
4988	TR315	W1H1AA-13	F4/Q1
4988	TR379	W1H1AA-13	F3/Q1
4988	TR501	W1H1AA-13	F4/NA
4988	TR502	W1H1AA-13	F4/NA
4988	TR503	W1H1AA-13	F1/Q1
4988	TR504	W1H1AA-13	F1/Q1
4988	TR530	W1H1AA-13	F4/NA
4988	TR545	W!RQZP-	F1/Q1
4988	TR552	W1H1AA-DP	F1/Q1
4988	TR609	W1H1AA-13	F3/Q1
4988	TR615	W1H1AA-13	F1/Q1
4988	TR700	W1H1AA-DP	F1/Q1

Water

Water Source / Treatmnt

Wtr Source-Np

Water Well Np

F1/Q1/NA

SITEUID

FACNO

UIC

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	124	W1H1AA-13	F1/Q1
------	-----	-----------	-------

Water Storage

Wtr Stor-Pot

Wat Str Tk Pot

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	254	W1H1AA-13

F3/Q4

Water Tank was built in 1942.

4988	363	W1H1AA-13
------	-----	-----------

F4/Q4

Water Storage Tank was built in 1943.

4988	385	W1H1AA-13
------	-----	-----------

F3/Q4

Water Storage Tank was built in 1948. The site has been impacted by developments that cause settlement of the system.

4988	WST34	W1H1AA-13
------	-------	-----------

F1/Q1

Wtr Stor-Np

Wat Str Tk Np

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	122	W1H1AA-13

F1/Q1

4988	123	W1H1AA-13
------	-----	-----------

F1/Q1

4988	WST01	W!RQZP-
------	-------	---------

F1/Q1

4988	WST02	W!RQZP-
------	-------	---------

F1/Q1

4988	WST03	W1H1AA-DP
------	-------	-----------

F1/Q1

Wat Retain Bas

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
<u>Msn-Func/Quality Rating</u>	<u>Asset Use Comments</u>

Wat Retain Bas

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	WRB04	W1H1AA-13	F1/Q1
4988	WRB05	W1H1AA-13	F1/Q1
4988	WRB06	UNASGD-	F1/Q1
4988	WRB34	W1H1AA-13	F1/Q1

Water Distribution

Wtr Lines-Pot

Water Dist Pot

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	WP400	W1H1AA-DP	F4/Q4

Fir Prot Lns-Np

Fir Prot Sys Np

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	FS609	W1H1AA-13	F1/Q1
4988	WF545	W!RQZE-	F1/Q1

Wtr Lines-Np

Water Distribution Lines, Nonp

F3/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	WP401	W1H1AA-13	F3/Q4

Sewer

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Wastewater Collection

Sew/Wst Lines

Sanitary Sewer

F4/Q4/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	SN360	W1H1AA-13	F3/Q3
4988	SS358	W1H1AA-13	F4/Q4

Road & Trail Netwk (Util)

Parking - Non-Org

Parking-Nonorg

Nonorg Pk Pavd

F1/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>	
4988	1003	W1H1AA-20	F1/NA
4988	66	W1H1AA-18	NA/NA Area currently used as storage for DMWR Outdoor Recreation Rental.
4988	OP600	W1H1AA-13	NA/NA
4988	OP601	UNASGD	F1/Q1
4988	OP602	W1H1AA-13	F1/Q1
4988	OP603	W1H1AA-13	F1/Q1
4988	P1029	W1H1AA-37	NA/NA
4988	P1049	W1H1AA-	NA/NA No illumination, no signage, poor drainage.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>	<u>Msn-Func/Quality Rating</u>	<u>Asset Use Comments</u>
4988 P1060 W1H1AA-37	NA/NA		
4988 P1064 W1H1AA-37	NA/NA		
4988 P1068 W1H1AA-37	NA/NA		
4988 P1097 IEPRAN-01	NA/NA		
4988 P1140 W1H1AA-15	F1/NA		
4988 P1300 W1H1AA-13	NA/NA		
4988 P1304 W1H1AA-13	NA/NA		
4988 P1316 UNASGD-	NA/NA		
4988 P1326 W1H1AA-13	F1/NA		Unpaved, eroded, and unmarked.
4988 P1339 W1H1AA-13	NA/NA		
4988 P540A W1H1AA-13	NA/NA		
4988 P540B W1H1AA-13	NA/NA		
4988 PN007 W1H1AA-13	F1/NA		No signage, damaged pavement.
4988 PN021 UNASGD-	F4/Q1		
4988 PN025 W1H1AA-13	F1/NA		Barricaded area, not in use.

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	PN037	W1H1AA-13	NA/NA
4988	PN067	W1H1AA-13	F1/NA pavement damage, unmarked, no signage, no handicapped.
4988	PN100	W1H1AA-13	F4/Q1
4988	PN148	W1H1AA-13	NA/NA
4988	PN152	W1H1AA-13	NA/NA
4988	PN167	W1H1AA-13	F1/NA Large pot holes, no signage, damaged pavement.
4988	PN168	W1H1AA-13	NA/NA
4988	PN183	W1H1AA-13	NA/NA
4988	PN192	W1H1AA-13	F1/NA
4988	PN202	W1H1AA-13	F1/NA
4988	PN218	W1H1AA-13	NA/NA no illumination, no signage , damaged pavement.
4988	PN224	W1H1AA-13	NA/NA
4988	PN292	UNASGD-	NA/NA
4988	PN294	W1H1AA-13	F4/NA
4988	PN314	W1H1AA-13	F1/NA

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	PN315	W1H1AA-13	F1/NA
4988	PN348	W1H1AA-13	F1/NA
4988	PN353	W1H1AA-13	F4/NA
4988	PN354	W1H1AA-13	F4/NA
4988	PN355	W1H1AA-13	F4/NA
4988	PN363	W1H1AA-13	F1/NA
4988	PN376	W1H1AA-13	F1/NA CLOSED DUE TO ATFP CRITERIA
4988	PN390	W1H1AA-13	F1/NA
4988	PN399	W1H1AA-13	F1/NA
4988	PN501	W1H1AA-13	F1/NA
4988	PN507	W1H1AA-13	F1/NA Undergoing repair work.
4988	PN511	W1H1AA-13	F4/Q1
4988	PN514	W1H1AA-13	F1/NA
4988	PN519	W1H1AA-13	F1/NA Parking area is barricaded, not in use based on ATFP criteria
4988	PN528	W1H1AA-13	NA/NA

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

4988	PN541	W1H1AA-13	NA/NA	
4988	PN545	WTJ2AA-00	F1/Q1	
4988	PN547	WTJ2AA-00	F1/Q1	
4988	PN556	W1H1AA-12	F4/NA	
4988	PN566	IEPRAN-01	F1/Q1	Not used as parking anymore. Photovoltaic farm and wind turbine site.
4988	PN606	W1H1AA-13	NA/NA	
4988	PN607	W1H1AA-13	F1/NA	
4988	PN608	W1H1AA-13	F1/Q1	
4988	PN611	W1H1AA-13	NA/NA	
4988	PN614	W1H1AA-13	F1/NA	
4988	PN660	W1H1AA-13	NA/NA	
4988	PN670	W1H1AA-13	NA/NA	
4988	PN689	IAAFES-00	F1/NA	
4988	PN700	W1H1AA-DP	F3/NA	

Mobility

Road & Trail Netwk (Mob)

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

Facility Class/Category/SubCat/FCG/CATCODE:

Msn-Func/Quality/Quantity Rating

Msn-Func/Quality Rating

Asset Use Comments

Surfaced Roads

Roads Surfaced

Roads, Paved

F4/Q3/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	613RD	W1H1AA-DP

F4/Q3

4988	RD402	W1H1AA-13
------	-------	-----------

F1/Q1

4988	RP401	W1H1AA-13
------	-------	-----------

F4/Q3

Damages caused by CAT 5 hurricane Maria, September 2017, include perimeter fence at perimeter road and golf course fence damages.

4988	RS362	W1H1AA-13
------	-------	-----------

F1/Q1

Vehicle Bridges

Vehicle Bridge

F2/Q1/NA

<u>SITEUID</u>	<u>FACNO</u>	<u>UIC</u>
4988	157	W1H1AA-X

F1/Q1

4988	364	W1H1AA-X
------	-----	----------

F1/Q1

4988	500	W1H1AA-X
------	-----	----------

F4/Q1

4988	542	W1H1AA-X
------	-----	----------

F4/Q1

4988	543	W1H1AA-X
------	-----	----------

F1/Q1

4988	602	W1H1AA-X
------	-----	----------

F1/Q1

4988	603	W1H1AA-X
------	-----	----------

F1/Q1

FOR OFFICIAL USE ONLY

Asset Use Ratings and Comments – By CATCODE

(ISR-Infrastructure)

(Permanent/Semi-permanent Asset Only)

Report Year: 2019

Data Date: 10/15/2018 6:18:00PM

Base Name: RQ137 - Fort Buchanan

<u>Facility Class/Category/SubCat/FCG/CATCODE:</u>	<u>Msn-Func/Quality/Quantity Rating</u>
	<u>Msn-Func/Quality Rating</u>
	<u>Asset Use Comments</u>

4988	900	W1H1AA-X	F1/Q1
4988	901	W1H1AA-X	F4/Q1
4988	910	W1H1AA-X	F1/Q1
4988	911	W1H1AA-X	F1/Q1

Parking - Org

Parking-Org

<u>Org Park Paved</u>	<u>F2/Q1/NA</u>
<u>SITEUID</u> <u>FACNO</u> <u>UIC</u>	
4988 613FL W1H1AA-DP	F1/NA
4988 OP037 W1H1AA-12	F1/Q1
4988 OP504 W1H1AA-13	NA/NA
4988 OP527 W1H1AA-34	NA/NA
4988 OP528 W1H1AA-13	F4/Q1
4988 OP550 WTJ2AA-00	F4/Q1
4988 OP597 W1H1AA-13	NA/NA
4988 OP609 UNASGD-	F1/Q1
4988 PN511 UNASGD	F4/Q1

FOR OFFICIAL USE ONLY